


1/12

FIG. 1



2/12

FIG.2




FIG.3

POWER SAVING MODE	RETURN TIME
a	0
b	1
c	3

3/12

FIG.4





FIG.6

JOB TO BE EXECUTED	DIFFERENCE TIME
A	5
B	1
C	15
D	3
E	5

4/12


FIG.5



10030270.010202

5/12

FIG. 7



6/12

FIG.8






FIG.9



8/12

FIG. 10



10030270.010200

10/030270

CEBON ET AL (783) 413-3000


DOCKET # 24764808 SHEET 9 OF 12

9/12

FIG.11


JOB TO BE EXECUTED	DIFFERENCE TIME	PERMITTED ERROR TIME
A	5	2
B	1	4
C	15	0
D	3	4
E	5	4

FIG.12



11/12

FIG.13



20201001020270

12/12

FIG.14

(a)

C	→	POWER SAVING MODE	RETURN TIME
6		A	5
4		B	16
		D	3
		E	5

(b)

	POWER SAVING MODE	RETURN TIME	
	A	5	
	B	1	4
	C	15	
	D	3	
	E	5	

(c)

POWER SAVING MODE	RETURN TIME
A	5
B, C	16
D	3
E	5